Consult Your State DOT For The Most Up-To-Date Status Of Bridges Structurally Deficient Bridges on the National Highway System 1st Congressional District of New Mexico, 2003 Rio Ranche 20 (423) Petroglyph NMON Albuquerque (556 18 South Valley Location I-25 SBL/TRAMWAY Structure Number 00000000005702 000000000005820 I-25 SBL IRR/I-25 NBL JUNCTION I-25/NM-473 000000000005821 IRR/I-25 SBL JUNCTION I-25/NM-473 0.5 MI S OF JCT I-25/I-40 000000000005989 I-25 NBL I-25 NBL I-25 AT LOMAS BLVD 000000000005991 1.9 MI W OF JCT I-25 I-25/MONTGOMERY BLVD 000000000006224 NM500 EB RIO BRAVO MONTGOMERY/EBL.WBL 0000000000006261 000000000006264 LOUISIANA BLVD NBL I-40/LOUISIANA BLVD LOUISIANA BLVD SBL I-25 NBL JCT I-25/LOUISIANA BLVD 0.6 MI N OF JCT I-40 WBL 000000000006265 10 000000000006496 11 000000000006567 125SB RMP TO 140EB I-25 / I-40 INTERCHANGE N COORS BLVD SBL NM-556 000000000006593 I-40 & COORS BLVD INTRCHG 2.24 MI W OF I-25 13 14 000000000006651 000000000006753 I-40 WBL ALBUQ/WEST MESA INTERCHNG 60 15 16 000000000007108 NM-500/RIO BRAVO 0.11 MI W OF NM-47/BRDWAY 000000000007379 1-25 NBL 16.2 MI N OF JCT NM-6 16.2 MI N OF JCT NM-6 11.6 MI E JCT I-25/I-40 00000000007380 I-25 SBL 18 0000000000007640 1-40 EBL 000000000008509 6.8 MI N OF JCT I-40 I-25 SBL 6.8 MI N OF JCT I-40 000000000008510 I-25 NBL Salinas Pueblo Missions NMON 54 Legend









U.S. Department of Transportation Bureau of Transportation Statistics Federal Highway Administration